



photo #  
051107-2  
Nov 2005

**NORTH** →

Ground is relatively flat  
with slight slope upwards  
to the north-northeast

Future Building (approx)

South Fence

West Fence

North property Line

Well Pad

No shift in land height at property line (no retaining wall)  
Ground was originally level between the two properties

**1050 Acacia - Montara - Nov 2005**  
San Mateo County, CA

**Exhibit**  
**A-02 Rev-0**

This exhibit shows that the original ground (natural grade) was relatively flat. The grade slopes upward slightly to the north-northeast. Slope increases near the North property line. Compare the ground grade to the top & bottom of west fence (which are level) for verification. This exhibit, combined with others, also proves that there was no retaining wall at the South property line, the ground was level across the property line. The County claim of a retaining wall at the South property line (Exhibit C28 para 6) is false. The County has claimed that there were large slopes in the ground at the back of the lot (Exhibit C8 para 6) and that the lot was not relatively flat (Exhibit C28 para 5 & 7). These false claims by the County form a critical basis for the County's fraudulent analysis of the fill depths, house height and the 2000 Survey accuracy.

For more info: [www.1050Acacia.info](http://www.1050Acacia.info)