



The Contractor added deep dirt fill on the lot: fill depth is over 2' at the Northwest corner of the house and about 3' at the Southwest corner. The added fill changed the grade so that now most drainage flows to the West fence, instead of to the south-southwest. Approved plans show no fill dirt (except a few inches around foundation). Approved plans explicitly state: "No site grading required except for minor adjustments..." (Exhibit D2 - Dwg A.2.1). Fill dirt violates Zone Reg 6300.2.6 and Grading Ordinance 8602.1.

For more info: [www.1050Acacia.info](http://www.1050Acacia.info)